

From: [Rauscher, Jon](#)
To: [Edlund, Carl](#); [Gray, David](#)
Cc: [Meyer, John](#); [Coltrain, Katrina](#); [Banipal, Ben](#); [Carroll, Craig](#); [Smith, Monica](#); [Smalley, Bryant](#); [Sanchez, Carlos](#); [Josiam, Raji](#)
Subject: RE: Write-up for US Oil Recovery UPDATED
Date: Wednesday, September 27, 2017 3:55:04 PM
Attachments: [US Oil Recovery UPDATED v2.docx](#)
[image00001.png](#)

<!--[if lte mso 15 || CheckWebRef]-->

Rauscher, Jon has shared a OneDrive for Business file with you. To view it, click the link below.

 [US Oil Recovery UPDATED v2.docx](#)

<!--[endif]-->

Summary with opening paragraph adjusted

From: Edlund, Carl
Sent: Wednesday, September 27, 2017 3:13 PM
To: Gray, David <gray.david@epa.gov>; Rauscher, Jon <Rauscher.Jon@epa.gov>
Cc: Meyer, John <Meyer.John@epa.gov>; Coltrain, Katrina <coltrain.katrina@epa.gov>; Banipal, Ben <banipal.ben@epa.gov>; Carroll, Craig <Carroll.Craig@epa.gov>; Smith, Monica <smith.monica@epa.gov>; Smalley, Bryant <smalley.bryant@epa.gov>
Subject: FW: Write-up for US Oil Recovery UPDATED

Shouldn't we also include the spill report information? E.G. Here is how I would adjust the opening paragraph

The U.S. Oil Recovery (USOR) site is located in Pasadena, Texas and consists of two separate properties north of Highway 225. On August 29, 2017 Responsible Parties reported that the portion of the site at 200 North Richey [a former municipal water treatment facility] was flooded due to Harvey and that an unknown amount of material was released. On September 4, 2017 EPA staff conducted an on-site inspection on to assess the site conditions of both the former water treatment facility at 200 North Richey and the former waste oil recycling facility at 400 North Richey. EPA directed the responsible parties to secure the sites and collect soil and water samples. On September 9, responsible parties reported that on September 6, 2017 there was a spill of storm water from the 200 North Richey facility of unknown quantity. Also on September 9, responsible parties reported a 200 gallon discharge of storm water from the 200 North Richey site. On September 13, in response to inquiries about a possible oil spill, an EPA On Scene Coordinator conducted an inspection of nearby Vince Bayou and did not find any evidence of a black oily discharge or material from the site.

.

From: Rauscher, Jon
Sent: Wednesday, September 27, 2017 1:06 PM

To: Gray, David <gray.david@epa.gov>

Cc: Edlund, Carl <Edlund.Carl@epa.gov>; Meyer, John <Meyer.John@epa.gov>; Coltrain, Katrina <coltrain.katrina@epa.gov>; Banipal, Ben <banipal.ben@epa.gov>

Subject: Write-up for US Oil Recovery UPDATED

Updated summary